

SUMMARY INSPECTION REPORT

Sample Park - Sample Park Outdoor Play Area

01 July 2015



This report was generated by:

Small World Inspections Sample Report

Inspection was carried out by:


Mel Campbell



Annual Outdoor Playgrounds

Summary Sheet

The following risks have been found:

Item: Cableway - Spring stopper		
	Hazard	Control Measure
	Broken stopper	Replace stopper

Report Detail

Facility Name	Site	Facility Type	Report	Date
Sample Park Outdoor Play Area	Sample Park	Outdoor Playgrounds	Annual	01/07/2015

Overview Image



Comments

This inspection should be conducted on an annual basis beginning in July 2015

Seal



Details

Name: Mel Campbell
 Email Address: smallworldapp+inspector@icloud.com
 Registration Number: 1061A

Equipment: Balance Beam Rocker

Image	Details	Comments
-------	---------	----------



Equipment Type: Rockers
 Manufacturer: Ledon
 Installation Date:
 Compliant: Yes
 Inclusive: No
 Compliance: Outdoor
 BS EN 1176
 Surface: Unknown
 Priority: 1 / Quality: 10


Equipment: Basket Swing

Image	Details	Comments
-------	---------	----------




Equipment Type: Swings
 Manufacturer: Playdale Playgrounds Limited
 Installation Date:
 Compliant: Yes
 Inclusive: Yes
 Compliance: Outdoor
 BS EN 1176
 Surface: Unknown
 Priority: 1 / Quality: 10

Equipment: Bin

Image	Details	Comments
	Equipment Type: Ancillary Manufacturer: Not applicable Installation Date: Compliant: Yes Inclusive: No Compliance: NONE Surface: Unknown Priority: 1 / Quality: 10	

Equipment: Bouncing Disc


Image	Details	Comments
	Equipment Type: General Manufacturer: Island Leisure Installation Date: Compliant: Yes Inclusive: No Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	

Component: Base

Top accordion

Design & manufacture


Structural integrity



Is the unit structurally sound

NO

Equipment: Cableway

Image	Details	Comments
	Equipment Type: Cableways Manufacturer: Playdale Playgrounds Limited Installation Date: Compliant: No Inclusive: No Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 8 / Quality: 3	

Component: Spring stopper

Safety Requirements

Design & Manufacture

Structural Integrity


Is the unit structurally sound

NO No Image



Is the item safe?

NO

	Hazard	Potential Harm	Risk Level Score (P×S)	Control Measure	Residual Risk Score (P×S)	Maintaining Control
 P 7 Q 3	Broken stopper	Falls, cuts and bruises	Probability 3 × Severity 3 9	Replace stopper	Probability 1 × Severity 1 1	Regular routine inspections


Component: Traveller



Is the unit structurally sound

NO


Equipment: Cradle Swings

Image	Details	Comments
	Equipment Type: Swings Manufacturer: Playdale Playgrounds Limited Installation Date: Compliant: Yes Inclusive: Yes Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	


Equipment: Dish Roundabout

Image	Details	Comments
	Equipment Type: Carousels Manufacturer: Sutcliffe Play Limited Installation Date: Compliant: Yes Inclusive: Yes Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	

Equipment: Fencing

Image	Details	Comments
	Equipment Type: Ancillary Manufacturer: NK Fencing Installation Date: Compliant: Yes Inclusive: No Compliance: NONE Surface: Unknown Priority: 1 / Quality: 10	

Equipment: Flat Swings


Image	Details	Comments
	Equipment Type: Swings Manufacturer: Playdale Playgrounds Limited Installation Date: Compliant: Yes Inclusive: No Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	

Component: Chains

Top Accordion

Design & Manufacture


Consumable components




Is it possible to replace damaged components prone to wear?

NO


Equipment: Gates

Image	Details	Comments
	Equipment Type: Ancillary Manufacturer: NK Fencing Installation Date: Compliant: Yes Inclusive: No Compliance: NONE Surface: Unknown Priority: 1 / Quality: 10	

Equipment: Rope Climber

Image	Details	Comments
	Equipment Type: General Manufacturer: Playdale Playgrounds Limited Installation Date: Compliant: Yes Inclusive: No Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	


Equipment: Seats

Image	Details	Comments
	Equipment Type: Ancillary Manufacturer: Playdale Playgrounds Limited Installation Date: Compliant: Yes Inclusive: Yes Compliance: NONE Surface: Unknown Priority: 1 / Quality: 10	


Equipment: See Saw Rocker

Image	Details	Comments
	Equipment Type: Rockers Manufacturer: Fahr Installation Date: Compliant: Yes Inclusive: No Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	


Equipment: Signage

Image	Details	Comments
	Equipment Type: General Manufacturer: Not Available Installation Date: Compliant: Yes Inclusive: Yes Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	


Equipment: Surfacing

Image	Details	Comments
	Equipment Type: Surfacing Manufacturer: Garden Escapes Installation Date: Compliant: Yes Inclusive: Yes Compliance: Surfacing BS EN 1177 Surface: Unknown Priority: 1 / Quality: 10	


Equipment: Toddler Multi Unit

Image	Details	Comments
	Equipment Type: General Manufacturer: Playdale Playgrounds Limited Installation Date: Compliant: Yes Inclusive: No Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	

Equipment: Tower Multi Unit

Image	Details	Comments
	Equipment Type: General Manufacturer: Playdale Playgrounds Limited Installation Date: Compliant: Yes Inclusive: No Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	

Equipment: Traditional Roundabout

Image	Details	Comments
	Equipment Type: Carousels Manufacturer: Hags/SMP Limited Installation Date: Compliant: Yes Inclusive: Yes Compliance: Outdoor BS EN 1176 Surface: Unknown Priority: 1 / Quality: 10	

